

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D0985648	(X3) Date Survey Completed 01/08/2019
Name of Provider or Supplier Melbourne Dermatology Center	Street Address, City, State 333 E Sheridan Rd, Melbourne, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3011	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, the laboratory failed to dispose of chemicals per manufacturer's instructions for 2 out of 2 years, (1/8/17 to 1/8/19) reviewed. Findings: Review of the manufacturer's instructions on the bottles of Bluing Reagent, Clear-Rite 3, Eosin-Y, Flex 100, Hematoxylin 7211, and 70% Dehydrant all stated, "Dispose of contents/container to an approved waste disposal plant." During an interview on 1/8/19 at 1:22 PM, Mohs Technician confirmed that the chemical reagents are disposed in the sink drain.</p>