

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1038878	(X3) Date Survey Completed 06/19/2018
Name of Provider or Supplier Reliance Pathology Partners Llc	Street Address, City, State 516 Vonderburg Dr, Brandon, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5429	<p>MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(a)(1)</p> <p>For unmodified manufacturer's equipment, instruments, or test systems, the laboratory must perform and document maintenance as defined by the manufacturer and with at least the frequency specified by the manufacturer.</p> <p>This STANDARD is not met as evidenced by: Based on maintenance log record review and interview with the Histotechnologist, the laboratory failed to document cleaning for the cryostat and microscope for two out of two years reviewed (2017-2018). Findings included: A review of the maintenance logs revealed no documentation of cleaning of the cryostat and microscope for two out of two years (2017 - 2018). An interview on 06/19/18 at 12:15 pm with the Histotechnologist confirmed that documentation had not been made for cleaning the cryostat and microscope for two out of two years (2017-2018).</p>