

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D1094272	<b>(X3) Date Survey Completed</b>  06/28/2018
<b>Name of Provider or Supplier</b>  Aqua Dermatology Of Florida Pa	<b>Street Address, City, State</b>  4180 Us 27 South, Sebring, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D3011</b>	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on observation and interview with the Lab Specialist, the laboratory failed to dispose of the Eosin Y, Hematoxylin, Clear-Rite, and the alcohol per the disposal instructions on the label of the reagents for two of two (2017-2018) years reviewed. Findings Included: A tour of the laboratory on 06/28/18 at 12:00 PM, revealed the Eosin Y, Hematoxylin, Clear - Rite, and alcohol reagents had label instructions that documented "Dispose of contents/container to an approved waste disposal plant." On 06/28/18 at 12:10 PM, the Lab Specialist stated that the Eosin Y, Hematoxylin, Clear-Rite, and the alcohol was disposed of down the drain of the sink with lots of water.</p>