

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D1099045	(X3) Date Survey Completed 11/01/2018
Name of Provider or Supplier Dermatology Southeast - Sunbeam	Street Address, City, State 4727 Sunbeam Rd Ste 102, Jacksonville, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A recertification survey was conducted on November 1, 2018. Southside Dermatology clinical laboratory had one deficiency found at the time of the visit.
D5413	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(b)</p> <p>The laboratory must define criteria for those conditions that are essential for proper storage of reagents and specimens, accurate and reliable test system operation, and test result reporting. The criteria must be consistent with the manufacturer's instructions, if provided. These conditions must be monitored and documented and, if applicable, include the following: (1) Water quality. (2) Temperature. (3) Humidity. (4) Protection of equipment and instruments from fluctuations and interruptions in electrical current that adversely affect patient test results and test reports.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview, it was determined that the humidity of the laboratory room to assure optimal operating conditions of the histopath equipments was not checked daily for 2 of the 2 years documents reviewed. Findings included: Review of the laboratory's procedure and logbook indicated that the humidity of the room needed to be recorded daily with a normal range of less than 60 %. There was no humidity record found on the logbook for 2 years from November 2016 to 2018. Interview on 11/1/18 at 11:30 AM, testing person # 1 confirmed that the humidity of the laboratory room was not checked and recorded daily.</p>