

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D2059389	<b>(X3) Date Survey Completed</b>  11/15/2018
<b>Name of Provider or Supplier</b>  Skin Cancer Center Of Central Florida	<b>Street Address, City, State</b>  10973 Se 175th Place #100, Summerfield, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D3011</b>	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on record review and interview with the Laboratory Manager, the laboratory failed to dispose of chemicals per manufacturer's instructions for 2 out of 2 years (2017-2018) reviewed. Findings Include: Review of the manufacturer's instructions on the bottles of alcohol, eosin, and xylene substitute all state that they should be disposed of in a waste disposal plant. During an interview on 11/15/18 at 11:00 AM' the Laboratory Manager confirmed that the alcohol, eosin, and xylene substitute are disposed of down the sink drain.</p>