

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  10D2092107	<b>(X3) Date Survey Completed</b>  09/08/2025
<b>Name of Provider or Supplier</b>  Advanced Dermatology And Cosmetic Surgery	<b>Street Address, City, State</b>  600 W Plymouth Ave, Deland, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	An announced recertification survey was conducted at Advanced Dermatology & Cosmetic Surgery on 9/8/25. The laboratory is not in compliance with 42 CFR Part 493, Requirements for Laboratories.
<b>D5417</b>	<p>TEST SYSTEMS, EQUIPMENT, INSTRUMENTS, REAGENT CFR(s): 493.1252(d)</p> <p>(d) Reagents, solutions, culture media, control materials, calibration materials, and other supplies must not be used when they have exceeded their expiration date, have deteriorated, or are of substandard quality.</p> <p>This STANDARD is not met as evidenced by: Based on observation and staff interview, the laboratory failed to ensure the potassium hydroxide (KOH) was not expired prior to patient testing. Findings include: Observations made during a tour of the laboratory on 9/8/25 at 10:00 AM, showed one bottle of "Potassium Hydroxide" with lot number 1342 expired 12/8/2023 During an interview on 9/8/25 at 10:05 AM with the Office Manager, it was confirmed the bottle of KOH was expired.</p>