

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 10D2121952	(X3) Date Survey Completed 05/15/2018
Name of Provider or Supplier Palm Harbor Dermatology Pa	Street Address, City, State 310 S Macdill Ave Ste 201, Tampa, FL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6094	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(5)</p> <p>The laboratory director must ensure that the quality assessment programs are established and maintained to assure the quality of laboratory services provided and to identify failures in quality as they occur.</p> <p>This STANDARD is not met as evidenced by: Based on laboratory record review and interview with the Histotechnologist, the Laboratory Director failed to maintain quality assurance activities. Findings included: During the laboratory record review, it was found that documentation of quality assurance activities were missing from the laboratory records. During an interview on 05/15/2018 at 10:15 AM, the Histotechnologist confirmed that the laboratory was not documenting quality assurance activities.</p>