

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 13D1046008	(X3) Date Survey Completed 12/05/2023
Name of Provider or Supplier Ip Twin Falls 1	Street Address, City, State 358 Cheney Dr W Ste 102, Twin Falls, ID	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5429	<p>MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(a)(1)</p> <p>For unmodified manufacturer's equipment, instruments, or test systems, the laboratory must perform and document maintenance as defined by the manufacturer and with at least the frequency specified by the manufacturer.</p> <p>This STANDARD is not met as evidenced by: Based on a review of laboratory maintenance logs, instrument manuals and an interview with the laboratory director (LD) on 12/5/2023, the laboratory failed to perform maintenance as required by the instrument manufacturer. The findings include: 1. A review of Beckman Coulter AU480 maintenance logs identified that the laboratory failed to perform the six month cleaning of the cuvettes and cuvette wheel in May 2022, May 2023 and November 2023 as required by the manufacturer. 2. An interview with the LD on 12/5/2023 at 10:58 am confirmed the above finding. 3. The laboratory reports performing 27,192 chemistry tests annually.</p>