

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 17D1014312	(X3) Date Survey Completed 09/14/2018
Name of Provider or Supplier Dermatology & Skin Cancer Centers	Street Address, City, State 11550 Granada Ln - 1st Floor, Leawood, KS	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3013	<p>FACILITIES CFR(s): 493.1101(e)</p> <p>Records and, as applicable, slides, blocks, and tissues must be maintained and stored under conditions that ensure proper preservation.</p> <p>This STANDARD is not met as evidenced by: Based on observation of slide storage and interview with laboratory staff, the laboratory failed to store slides under conditions that ensure proper preservation. Findings: 1. Observation of the slide storage area revealed a car garage with no temperature-controlled environment. Slides were exposed to extreme hot and cold environments. 2. Interview with laboratory staff on September 14, 2018 at 9:30 AM confirmed the laboratory failed to store histopathology slides under conditions that ensure proper preservation.</p>