

| | | |
|--|--|---|
| Statement of Deficiencies | (X1) Provider/Supplier/CLIA Identification Number 21D0216329 | (X3) Date Survey Completed 05/03/2022 |
| Name of Provider or Supplier Planned Parenthood-Md Annapolis Health Center | Street Address, City, State 929 West Street Suite 200, Annapolis, MD | |
| For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency. | | |

| (X4) ID Prefix Tag | Summary Statement of Deficiencies |
|---------------------------|--|
| D3011 | <p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor observation and interview with the Director of Risk and Quality Management, the laboratory did not ensure that an eye wash station was located in the laboratory area where testing occurs. Findings: 1. During a tour of the laboratory at 10:15 AM, it was observed that there was no eye wash station available in the laboratory where laboratory testing is performed. The laboratory's eye wash station was located on the other side of the facility. 2. During an interview on 05/03/2022 at 11:45 AM, the Director of Risk and Quality Management confirmed that the eye wash station was not located in the room where laboratory testing is performed.</p> |