

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 21D2159797	(X3) Date Survey Completed 08/14/2025
Name of Provider or Supplier Johns Hopkins Imaging At Green Spring Station	Street Address, City, State 10803 Falls Road Suite 1100, Lutherville, MD	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	Johns Hopkins Imaging at Green Spring Station is in substantial compliance with the conditions of participation for 42 CFR part 493 requirements for clinical laboratories.