

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D0871369	(X3) Date Survey Completed 05/18/2021
Name of Provider or Supplier Skin And Vein Center Livonia	Street Address, City, State 10984 Middlebelt Road, Livonia, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5803	<p>TEST REPORT CFR(s): 493.1291(b)</p> <p>Test report information maintained as part of the patient's chart or medical record must be readily available to the laboratory and to CMS or a CMS agent upon request.</p> <p>This STANDARD is not met as evidenced by: . Based on record review and interview with the Laboratory Liaison (LL), the laboratory failed to produce the patient paper chart for 1 (#12) of 13 charts reviewed for 2 years. Findings include: 1. Record review for 1 (#12) of 13 patient charts reviewed, the laboratory was unable to locate the paper chart to verify the final dermatopathology report was maintained in the chart. 2. An interview on 5/18/2021 at 11:00 am, the LL confirmed patient #12 the paper chart was not located on the day of the survey for the surveyor to verify results for the dermatopathology report.</p>