

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 23D2054540	(X3) Date Survey Completed 11/02/2021
Name of Provider or Supplier Wayne Health - Canfield And Tolan Park	Street Address, City, State 50 E Canfield Ste 101-S, Detroit, MI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3011	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: . Based on observation, record review, and interview with Testing Personnel #1 (TP1), the laboratory failed to establish safety procedures to ensure protection from hazardous materials for 1 (TP1) of 5 testing personnel listed on the CMS-209 form. Findings include: 1. The surveyor observed TP1 eating in laboratory on 11/2/21 at 9:14 am. 2. An interview on 11/2/21 at 9:14 am with TP1 confirmed they were eating in the laboratory. 3. A review of the laboratory's safety policies revealed a lack of policy about eating and drinking in the laboratory.</p>