

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 31D0122897	(X3) Date Survey Completed 05/20/2021
Name of Provider or Supplier Diosdado Non Medical Services, Llc	Street Address, City, State 525 Route 70, Brick, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5433	<p>MAINTENANCE AND FUNCTION CHECKS CFR(s): 493.1254(b)(1)</p> <p>For equipment, instruments, or test systems developed in-house, commercially available and modified by the laboratory, or maintenance and function check protocols are not provided by the manufacturer, the laboratory must establish a maintenance protocol that ensures equipment, instrument, and test system performance that is necessary for accurate and reliable test results and test result reporting. The laboratory must perform and document the maintenance activities specified in paragraph (b)(1)(i) of this section.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the Procedure Manual (PM) and interview with the Technical Supervisor (TS), the laboratory failed to ensure that microscope maintenance was performed from 12/14/2018 to the date of the survey. The finding includes: 1. The PM stated maintenance was required annually. 2. There was no evidence that maintenance was performed from 12/14/2018 to the date of survey. 3. The TS confirmed on 5/20/21 at 10:00 am that the laboratory did not ensure maintenance was performed.</p>