

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 31D0996014	(X3) Date Survey Completed 04/10/2018
Name of Provider or Supplier South Jersey Dermatology Center	Street Address, City, State 601 Route 37 West Suite 105, Toms River, NJ	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6094	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(5)</p> <p>The laboratory director must ensure that the quality assessment programs are established and maintained to assure the quality of laboratory services provided and to identify failures in quality as they occur.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of the laboratory's Quality Assurance (QA) Plan and interview with the Chief Executive Officer (CEO), the laboratory failed to maintain the Quality Assessment (QA) plan from 4/20/16 to the date of the survey. The finding includes: 1. The QA plan stated the Laboratory Director reviews all quality control charts and logs on a monthly basis but there was no documented evidence of review on any records. 2. The CEO confirmed on 4/10/18 at 10:35 am the QA plan was not maintained.</p>