

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D1088553	(X3) Date Survey Completed 04/14/2026
Name of Provider or Supplier New York Cosmetic Skin & Laser Surgery Center	Street Address, City, State 121 East 60th Street - Suite 8ab, New York, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5291	<p>GENERAL LABORATORY SYSTEMS QUALITY ASSESSMENT CFR(s): 493.1239(a)</p> <p>The laboratory must establish and follow written policies and procedures for an ongoing mechanism to monitor, assess, and, when indicated, correct problems identified in the general laboratory systems requirements specified at 493.1231 through 493.1236.</p> <p>This STANDARD is not met as evidenced by: Based on review of the New York Cosmetic Skin & Laser Surgery Center Standard Operating Procedure (SOP) manual, lack of Quality Assessment (QA) records, as well as interview with the Office Manager (OM), the laboratory failed to establish and follow written policies and procedures for an ongoing mechanism to monitor, assess, and, when indicated, correct problems identified in the general laboratory systems requirements. FINDINGS: 1. The New York Cosmetic Skin & Laser Surgery Center laboratory SOPs did not include a Quality Assessment (QA) policy. 2. There was no documentation of QA review performance for calendar years 2024 and 2025. 3. The OM confirmed the findings on April 14, 2026, at approximately 9:30 A.M.</p>