

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 33D2051133	(X3) Date Survey Completed 03/07/2019
Name of Provider or Supplier Moss Dermatology, Llc	Street Address, City, State 109-19 72nd Road Com1, Forest Hills, NY	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D5401	<p>PROCEDURE MANUAL CFR(s): 493.1251(a)</p> <p>A written procedures manual for all tests, assays, and examinations performed by the laboratory must be available to, and followed by, laboratory personnel. Textbooks may supplement but not replace the laboratory's written procedures for testing or examining specimens.</p> <p>This STANDARD is not met as evidenced by: Based on a lack of procedures and an interview with the laboratory director, the laboratory failed to have a procedure for equipment maintenance. Findings Include: The laboratory director confirmed on March 7, 2019, at approximately 10:45 am that the laboratory failed to have a procedure available indicating how often maintenance will be performed on the microscope.</p>