

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 38D0856477	(X3) Date Survey Completed 01/14/2020
Name of Provider or Supplier Adrienne Borg Nd	Street Address, City, State 74 East 18th Ave Suite 12, Eugene, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A survey of Adrienne Borg lab located at 74 East 18th Avenue Suite 12 in Eugene, OR was conducted on January 14th 2020. The laboratory was found to be in substantial compliance with the CLIA regulations (42 CFR, Part 493 effective April 24, 2003). No deficiencies were cited.