Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 38D2154056	(X3) Date Survey Completed 10/18/2022
Name of Provider or Supplier West Medford Health Clinic-La Clinica	**Street Address, City, State** 1307 W Main St, Medford, OR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	A special survey of West Medford Health Center - La Clinica located at 1307 West Main Street, Medford, OR. 97501 was conducted on October 18, 2022. The Laboratory was found to be in substantial compliance with the CLIA Condition-level regulation (42 CFR, Part 493.41) pertaining to COVID-19 reporting requirements. No deficiencies were cited.