

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D0194700	(X3) Date Survey Completed 04/12/2023
Name of Provider or Supplier Center For Dermatology Laser & Cosmetic Surgery	Street Address, City, State 915 Montgomery Ave, Suite 204, Narberth, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6094	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(e)(5)</p> <p>The laboratory director must ensure that the quality assessment programs are established and maintained to assure the quality of laboratory services provided and to identify failures in quality as they occur.</p> <p>This STANDARD is not met as evidenced by: Based on the lack of quality assurance (QA) documentation and interview with the laboratory's anatomic pathology consultant, the laboratory director (LD) failed to ensure a QA program was established and maintained to ensure the quality of services provided by the laboratory from 02/25/2021 to the date of the survey. Findings include: 1. On the date of the survey, 04/12/2023 at 10:30 am, the laboratory could not provide documentation for the periodic QA evaluation performed to assess the laboratory's pre-analytical, analytical, and post-analytical processes from 02/25/2021 to 04/12/2023. 2. The laboratory performed 2,678 histopathology examinations in 2022 (CMS-116 annual volume). 3. The laboratory's anatomic pathology consultant confirmed the findings above on 04/12/2023 around 12:00 pm.</p>