

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 39D2109579	(X3) Date Survey Completed 03/09/2020
Name of Provider or Supplier Carlisle Dermatology Group Llc	Street Address, City, State 41 Eastgate Drive, Carlisle, PA	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6046	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)</p> <p>(b) The technical consultant is responsible for-- (b)(8) Evaluating the competency of all testing personnel and assuring that the staff maintain their competency to perform test procedures and report test results promptly, accurately and proficiently.</p> <p>This STANDARD is not met as evidenced by: Based on laboratory personnel interview and review of the laboratory Testing Personnel records on the date of the survey, the Technical Consultant failed to evaluate the competency for 2 of 2 testing personnel. Findings include: 1. Review of the laboratory Testing Personnel records revealed no competency records for 2 of 2 Testing Personnel who performed KOH & Scabies tests, from 01/08/2019 through 03/09/2020 . 2. 97 KOH tests & 30 Scabies tests were performed from January 2019 through March 2020. 3. During the survey at 12:30 pm, the assistant office manager confirmed the above findings.</p>