

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D0658094	(X3) Date Survey Completed 08/11/2021
Name of Provider or Supplier Lab Clinico Guayanillense	Street Address, City, State Calle Munoz Rivera #135, Guayanilla, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The laboratorio Clinico Guayanillense, CSP was found to be in substantial compliance with CLIA regulations (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on August 11, 2021.