

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D0862653	(X3) Date Survey Completed 09/11/2025
Name of Provider or Supplier Laboratorio Clinico Nazarry Ii	Street Address, City, State Calle Javilla, Esquina Alfonzo Xii, San German, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The Laboratorio Clinico Nazarry II was found to be in substantial compliance with CLIA regulation (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on September 11, 2025.