

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D0957284	(X3) Date Survey Completed 04/19/2024
Name of Provider or Supplier Lab Clin Centro San Cristobal Villalba	Street Address, City, State Calle Munoz Rivera 40, Villalba, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The Laboratorio Clinico Centro San Cristobal Villalba was found to be in substantial compliance with CLIA regulations (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on April 19, 2024.