

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D0984957	(X3) Date Survey Completed 05/18/2021
Name of Provider or Supplier Laboratorio Clinico Almacigo	Street Address, City, State Carr 371 Km 1 Hm 7 Bo Almacigo, Yauco, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The laboratorio Clinico Almacigo was found to be in substantial compliance with CLIA regulations (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on May 18, 2021.