

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D1069513	(X3) Date Survey Completed 02/13/2020
Name of Provider or Supplier Laboratorio Clinico Cuba	Street Address, City, State Carr Pr-125 Km 5 Hm 2 Calle Barbosa 326, Moca, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The Laboratorio Clinico Cuba was found to be in substantial compliance with CLIA regulation (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on February 13, 2020.