

<b>Statement of Deficiencies</b>	<b>(X1) Provider/Supplier/CLIA Identification Number</b>  40D2003980	<b>(X3) Date Survey Completed</b>  12/10/2020
<b>Name of Provider or Supplier</b>  Laboratorio Clinico Rolon	<b>Street Address, City, State</b>  Road Pr 129 Km 2 Marginal Interior, Arecibo, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

<b>(X4) ID Prefix Tag</b>	<b>Summary Statement of Deficiencies</b>
<b>D0000</b>	The laboratorio Clinico Roln was found to be in substantial compliance with CLIA regulations (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on December 10, 2020.