

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D2069774	(X3) Date Survey Completed 05/04/2022
Name of Provider or Supplier Laboratorio Clinico Cayey	Street Address, City, State Carr Pr-1 Km 51, Hm 8, Cidra, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The Laboratorio Clinico Cayey was found to be in substantial compliance with CLIA regulation (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on May 4, 2022.