

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 40D2082435	(X3) Date Survey Completed 07/12/2024
Name of Provider or Supplier Laboratorio Clinico La 116	Street Address, City, State Centro Comercial Plaza Guanica, Bo Cano., Guanica, PR	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	The Laboratorio Clinico La 116 was found to be in substantial compliance with CLIA regulations (42 CFR Part 493, effective April 24, 2003). No deficiencies were cited as a result of an onsite survey performed on July 12, 2024.