

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 44D1016165	(X3) Date Survey Completed 10/12/2021
Name of Provider or Supplier Chattanooga Skin And Cancer Clinic	Street Address, City, State 6061 Shallowford Road, Chattanooga, TN	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D3011	<p>FACILITIES CFR(s): 493.1101(d)</p> <p>Safety procedures must be established, accessible, and observed to ensure protection from physical, chemical, biochemical, and electrical hazards, and biohazardous materials.</p> <p>This STANDARD is not met as evidenced by: Based on observation during a tour of the histopathology work area, observing a pungent chemical odor and interview with the Medical Director, the laboratory failed to install a biohazard fume hood to protect against exposure of hazardous chemicals, for the year 2019, 2020 and 2021. Findings include: 1. On October 12, 2021 at approximately 10:00am the histopathology work area was observed and no biohazard fume hood was present in the staining area. 2. There was a also a strong pungent chemical odor, noticed while touring the histopathology area on October 12, 2021 approximately 10:00am. 3. In an interview, on October 12, 2021 at approximately 10:00am, the Medical Director confirmed the histopathology lab was not equipped with a biohazard fume hood.</p>