

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 45D1094692	(X3) Date Survey Completed 05/28/2019
Name of Provider or Supplier Pain & Spine Center	Street Address, City, State 5652 N Mesa Street, El Paso, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6079	<p>LABORATORY DIRECTOR RESPONSIBILITIES CFR(s): 493.1445(a)(b)</p> <p>The laboratory director is responsible for the overall operation and administration of the laboratory, including the employment of personnel who are competent to perform test procedures, record and report test results promptly, accurately and proficiently, and for assuring compliance with the applicable regulations. (a) The laboratory director, if qualified, may perform the duties of the technical supervisor, clinical consultant, general supervisor, and testing personnel, or delegate these responsibilities to personnel meeting the qualifications under 493.1447, 493.1453, 493.1459, and 493.1487 respectively. (b) If the laboratory director reapportions performance of his or her responsibilities, he or she remains responsible for ensuring that all duties are properly performed.</p> <p>This STANDARD is not met as evidenced by: Review of quality control records, policies and procedures, patient test records and interview of facility personnel during the on-site revisit conducted on May 28, 2019 found this deficiency remains uncorrected. The laboratory director failed to ensure that the quality control program had been established and maintained. (See D5217, D5441 and D5481)</p>