

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 45D2187621	(X3) Date Survey Completed 05/21/2021
Name of Provider or Supplier Advanced Diagnostic Laboratory	Street Address, City, State 1077 Central Parkway S, Suite 200, San Antonio, TX	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D0000	An unannounced investigation of complaint TX00376487 conducted on site on 05/21/2021. The facility was found to be in substantial compliance with all CLIA conditions and standards surveyed. No deficiencies cited. Complaint TX00376487 is unsubstantiated.