

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 52D0393122	(X3) Date Survey Completed 06/04/2024
Name of Provider or Supplier Muscodah Health Center	Street Address, City, State 1075 N Wisconsin Ave, Muscodah, WI	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies
D6047	<p>TECHNICAL CONSULTANT RESPONSIBILITIES CFR(s): 493.1413(b)(8)(i)</p> <p>The procedures for evaluation of the competency of the staff must include, but are not limited to direct observations of routine patient test performance, including patient preparation, if applicable, specimen handling, processing and testing.</p> <p>This STANDARD is not met as evidenced by: Based on surveyor review of competency assessment records and interview with the technical consultant, the technical consultant did not document site specific direct observation of routine patient testing for nine of ten clinic testing personnel in 2022 and 2023. Findings include: 1. Review of competency assessment records showed no evidence of direct observation performed at this clinic site for testing personnel. 2. Interview with the technical consultant on June 4, 2024, at 10:30 AM confirmed the technical consultant did not document direct observation at this clinic site for routine testing of testing personnel.</p>